



Note
Ubenævnte mål er i m
Koter er angivet i forhold til DVR90
Koordinater er angivet i forhold til UTM32/ETRS89

Nye geotekniske boringer er omtrentlig placeret
Endelig placering koordineres med grundejer

- Signaturer**
-  nr. Nye geotekniske boringer med mulighed for pejlelogger
 -  nr. Eksisterende boringer, se bilag 4 (SWECO/Franck, 2024)
 -  nr. Eksisterende boringer, se bilag 3 (A&H, 2021)
 -  nr. Historiske boringer, nedlagt, se bilag 2 (Grontmij/SWECO, 2011)

Geotekniske boringer			
Boringsnr.	Dybde	X-Koordinat	Y-Koordinat
BA1	7 m.u.t	591498.08	6355808.35
BA2	7 m.u.t	591497.12	6355762.21
BA3	7 m.u.t	591492.58	6355748.48
BA4	7 m.u.t	591457.97	6355749.86
BA5	7 m.u.t	591449.01	6355734.37

Rev.	Dato	Init.	Vedr.
-	-	-	-
-	-	-	-
-	-	-	-

Sag	Frederikshavn Kommune, Vandløbsrestaurering, Sæby Vandmølle				Tegn. nr. 0.0.1
Emne	Situationsplan, Geotekniske boringer				
Mål	1:500	Sag nr. 25.077	Init. NC/JSC	Dato 2026.06.17	

A1 Consult A/S
Stieg Larssons Alle 11 8920 Randers NV Tlf. 8641 8410
info@a1consult.dk www.a1consult.dk

